

FIG.5A





FIG.5B



A cross-sectional view of a mechanical assembly. A screw 10 is shown passing through a sleeve 45. The sleeve 45 is mounted on a shaft 49. The screw 10 has a head 46 and a threaded portion 47. The sleeve 45 has a central bore 50. The screw 10 is secured by a nut 51. The assembly is shown in a cross-sectional view with hatching indicating different materials. Labels include 10, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, and M5.